

HAND HELD WEED WIPER OPERATING INSTRUCTIONS

The Speidel Weed Wiper is designed to remove unwanted vegetation around buildings, fences, trees, yards, gardens, etc., using Roundup herbicide. The herbicide-water mixture is poured into the applicator's tube handle. It then soaks the canvas wiping surface which is used to rub a small amount of the herbicide mixture on unwanted vegetation. The tap valve is used to control the soaking rate of the canvas by increasing or decreasing the amount of air that can enter the tube.

TO ASSEMBLE: Screw the two sections of handle together. Screw the applicator end to the bottom end of handle and the tap to the top end. The new canvas will be slow to saturate at first. Soak the canvas with water from a garden hose. Remove tap and fill the tube with water. Re-attach tap and open slightly. Scrub the wet canvas surface with a household brush to get the flow started before using herbicide mixture.

HERBICIDE MIXTURE: Mix clean water and herbicide at a rate of 2 parts water to 1 part Roundup for broadleaf weeds. A diluted mixture of 4 to 1 can be used for unwanted grass type vegetation. 10 ounces maximum of mixture will fill the applicator. Overfilling may possibly prevent shutoff. Open the tap only enough to provide sufficient wetness on the canvas surface for good coverage, but not to the point of dripping. Depending on the growing conditions, a small amount of herbicide mixture on the leaf surface should kill the entire plant.

CLEANING: After use, empty the applicator completely. Thoroughly rinse the inside of the pipe and wash the outside of the canvas to remove all herbicide residue. Let dry before storing.